


# 3M™ Speedglas™ 9100 Welding Shield



Part no.	Description	Part no.	Description	Part no.	Description
50 11 05	Welding shield without SideWindows, with Speedglas 9100V filter, variable shade 5, 8, 9-13.	50 11 25	Welding shield without SideWindows, with Speedglas 9100XX filter, variable shade 5, 8, 9-13.	50 18 15	Welding shield with SideWindows, with Speedglas 9100X filter, variable shade 5, 8, 9-13.
50 11 15	Welding shield without SideWindows, with Speedglas 9100X filter, variable shade 5, 8, 9-13.	50 18 05	Welding shield with SideWindows, with Speedglas 9100V filter, variable shade 5, 8, 9-13.	50 18 25	Welding shield with SideWindows, with Speedglas 9100XX filter, variable shade 5, 8, 9-13.



## Accessories and spare parts Speedglas 9100 Welding Shield

Part no.	Description	Part no.	Description	Part no.	Description
16 80 15	Comfort sweatband, pkg of 3.	50 11 90	Speedglas 9100 shield without SideWindows without headband	52 80 25	Inner protection plate for Speedglas 9100XX, pkg of 5. Plate marking 117x77.
16 90 05	Head protection, black TecaWeld.	50 18 00	Speedglas 9100 shield, with SideWindows with headband	53 10 00	Battery holder, pkg of 2
16 90 10	Neck protection, black TecaWeld.	50 18 90*	Speedglas 9100 shield, with SideWindows without headband	53 20 00	Heat reflecting silver front
16 91 00	Hood, black/grey TecaWeld.	52 60 00	Outer protection plate standard, pkg of 10.	53 20 15*	SideWindows cover plate (sticker), 2 pairs.
17 10 20	Magnifying lens 1.0.	52 70 00	Outer protection plate extra scratch resistant, pkg of 10.	53 30 00	Speedglas 9100 headband including assembly parts.
17 10 21	Magnifying lens 1.5.	52 70 70	Outer protection plate heat resistant pkg of 10.	53 60 00	Pivot mechanism, left and right.
17 10 22	Magnifying lens 2.0.	52 80 05	Inner protection plate for Speedglas 9100V filter, pkg of 5. Plate marking 117x50.	53 61 00	Headband front part.
17 10 23	Magnifying lens 2.5.	52 80 15	Inner protection plate for Speedglas 9100X, pkg of 5.	53 62 00	Headband back part.
17 10 24	Magnifying lens 3.0.	52 80 25	Inner protection plate for Speedglas 9100XX, pkg of 5. Plate marking 117x61.		
42 20 00	Battery, pkg of 2.				
50 00 05	Speedglas 9100V welding filter, variable shade 5, 8, 9-13				
50 00 15	Speedglas 9100X welding filter, variable shade 5, 8, 9-13				
50 00 25	Speedglas 9100XX welding filter, variable shade 5, 8, 9-13				
50 11 00	Speedglas 9100 shield without SideWindows with headband				

\* Please use part no. 50 18 90 when new SideWindows are required.